

TEST REPORT

No. : SZIN2306000976ML01-1_EN

Date : 2023-06-19

Page: 1 of 4

scan to see the report



SZIN2306000976ML01-1

CUSTOMER NAME: GUANGZHOU JINGNUO TECHNOLOGY DEVELOPMENT CO., LTD.
ADDRESS: 501-504, BUILDING A04, NO. 83, KAIYUAN AVENUE, HUANGPU DISTRICT, GUANGZHOU

Sample Name : Cam Lock Fitting

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Date of Receipt : 2023-06-08
Testing Period : 2023-06-08~2023-06-15
Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical
Services Co., Ltd. ShenZhen Branch.

Peter

Peter Lau
Authorized signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
Room 101-801, Plant 4 & Room 101, Plant 2 & Room 101, Plant 3 & Room 301-501, Plant 3, Jiangshao (Bantian) Industrial Plant Area, No. 430, Jihua Road, Bantian Community, Bantian Street, Longgang District, Shenzhen, Guangdong, China 518129 www.sgs.com.cn
中国·广东·深圳市龙岗区坂田街道坂田社区吉华路430号江潮(坂田)工业厂区厂房4号101-801、2号101、3号301-501 邮编:518129 t(86-755) 25328673 sgs.china@sgs.com

TEST REPORT

No. : SZIN2306000976ML01-1_EN

Date : 2023-06-19

Page: 2 of 4

1. Compression test of connecting fitting:



Reference method: GB/T 28203- 2011, clause 6.4.1

Test result:

Sample No.	Requirement	Result (N)	Conclusion
001	≥ 240 N	792	Pass

Note: The requirement is referred to GB/T 28203-2011, clause 5.4.1.

Test photo

	
Before test	During test
	
After test	Test curve

TEST REPORT

No. : SZIN2306000976ML01-1_EN

Date : 2023-06-19

Page: 3 of 4

2. Torque test of connecting fitting:

Reference method: GB/T 28203- 2011, clause 6.4.4



Test result

Sample No.	Requirement	Result (N.m)	Conclusion
001	≥4.0 N.m	8.5	Pass

Note:

1. The client claimed nominal diameter of the cam is 8 millimeters,
2. The requirement is referred to GB/T 28203- 2011, clause 5.4.4.

Test photo


	
Before test	During test

TEST REPORT


No. : SZIN2306000976ML01-1_EN

Date : 2023-06-19

Page: 4 of 4



After test



Sample Photo

Appendix information:

1. The test report shall only be used for clients' scientific research, teaching, internal quality control, product research and development, etc... and just for internal reference.
2. This test report updates Sample Name, supersedes the test report No. SZIN2306000976ML01_EN dated 2023-06-15, original report will be invalid from today.

*****End of report*****